



**Missouri DNR, Tanks Section
Summary Information
FFY 2021**

General Information

Public Record Posted Date

12/6/2021

Total Number of Active UST Sites: 3,278
Total Number of Active USTs: 8,503

Summary Information For On-Site Inspections

Inspection Timeframe: 10/1/20 to 9/30/21
Number of UST Facilities Inspected: 740
Percent Compliance (Combined Measure): 74.85%

*Tank, facility, and on-site inspection data is based on active underground storage tanks inspected during Federal Fiscal Year 2021. The on-site inspections Percent Compliance measure is based on the combined performance measure of the significant operational compliance (SOC) requirements.

Summary Information for Releases

Remediation Case Dates Added Timeframe: 10/1/20 to 9/30/21
Number of Remediation Cases Opened: 69

Source	Cause													
	Overfill		Spill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Totals	#	%	1	1.45%	1	1.45%	14	20.29%	3	4.35%	0	0.00%	0	0.00%
Tank	2	2.90%					2	2.90%						
Piping	6	8.70%					4	5.80%	2	2.90%				
Dispenser	5	7.25%					5	7.25%						
STP	2	2.90%					2	2.90%						
Delivery Problem	1	1.45%			1	1.45%								
Other	1	1.45%					1	1.45%						
Unknown	52	75.36%	1	1.45%					1	1.45%			50	72.46%

*Release, source, and cause information is based on releases from leaking underground storage tank sites. Source and cause data were collected from release reports submitted to the department.

*Site-specific information can be reviewed by downloading and searching the Missouri Department of Natural Resources

Underground Storage Tanks Database (online version) at: <https://dnr.mo.gov/document-search/source-cause-report-federal-fiscal-year-2021>

If you are unable to download and/or print this document and would like a copy, please contact Trisha Berve at Trisha.Berve@dnr.mo.gov or (573) 522-6140.